

GVR Center	Component (Asset)	Maintenance/Repair Work Required	Reserve Study Amount Funded in 2018		Q	Bid / Quote (\$)		Additional Funding Required	Funding Source
M-R-R RESERVE FUNDE	D PROJECTS - ADDITIONAL FU	INDING REQUIRED							
Continental Vistas	Pool	Pool needs to be replastered	\$	15,129	\$	25,735	\$	10,606	Operating Cash
West Center	Billiards Tables	Replace tables	\$	21,302	\$	27,353	\$	6,051	Operating Cash
West Center	Carpeting	Replace carpet in billiards room only	\$	13,297	\$	5,000			M-R-R Reserve
NON-CAPITAL FUNDING	ì								
Canoa Hills	Spa	Spa needs to be replastered		N/A	\$	4,537	\$	-	Facilities Operating Budget
EMERGENCY REPAIR									
Desert Hills	Electrical Service Entrance	Service entrance switchgear, transformer, & I-Line panel board needs to be replaced		N/A	ċ	55,717	ċ	55,717	Emergency Reserves